


# Spare Parts

## Common Spares

### M40 Gravograph Cutter for Traffolyte, 4mm text,

a balance, correct length cutter for low noise  
Cut M40 4mmH 4.36x125 1@95ex 3 @ 85ex



### IS200, IS400, IS6000 Vision

Cutter for Traffolyte, 4mm text, Gravograph

for these large spindles, balance cutter is not essential."

Cut ISxx 4mmH 4.36x135 1@85ex 3 @ 75ex  
Cut IS trade 10 cutters 4.36 10@\$67 ea ex  
Cut IS Diamond Rotate 1 @ \$180 ea ex  
Cut IS Diamond drag 1 1 @ \$110 ea ex



### 11/64 4.36 Gravograph TwinCut insert system

cut insert sleeve 1@165ex  
cut-insert 4mmH txt 1@ \$35ex  
cut-insert Dia drag 1@ \$35ex  
cut-insert Dia Rotate 1@ \$35ex



### M20v1 IM3

Cutter for Traffolyte, 4mm text, Gravograph

a balance, correct length cutter for low noise

Cut M20 4mmH 3.16x120 1@95ex  
Cut M20 Dia Drag 3.16x120 @ \$110ea ex  
Cut M20 Dia rotate 3.16x120 @ \$65ea ex  
Cut M20J Diamond B 3.16x10 @ \$110ea ex  
 (28187 M20J B)




### Laser Engraver Spares LS100 LS900

Spare LS100 clean kit  
 spare LS100 lens25mm 1 @ 95ex ea  
 spare LS100 mirror 25mm 1 @ 85ex ea  
 spare clean optice kit 1 @ 65  
 spare LS100 focus finger 1 @ 95 ea ex



### Laser Engraver Spares TM300 400 600 720

Spare Laser clean kit 1 @ 95ex ea  
 spare TM lens 1 @ 95ex ea  
 spare TM mirror mirror 25mm 1 @ 85ex ea  
 spare TM focus finger 1 @ 95ex ea



### Diamond None cone

#### M20 M40 IS200, IS400, IS6000 Vision

will screw on to all spindles

p/n cut Diamond Knearl 1@85 ea ex



#### Vac Nose Cone

Nose cone vac 3.3mm 21665 \$75 ea ex  
 Nose cone vac 8mm 21672 \$75 ea ex  
 Nose cone foot 12720 \$35 ea ex

#### Belt's

IM3 p/n 10100 295D \$45  
 IS200 p/n 13457 160mmD \$45  
 IS400 p/n15400 or 14246 90mmD \$45  
 IS6000 p/n14588 130mmD \$55  
 is6000xp p/n14643 160mmThick \$45  
 Grinder G p/n 13370 310D \$45

